

96-D Allen Boulevard Farmingdale, New York 11735-5626 USA Tel. +1 (631) 293-8944 Fax +1 (631) 293-8956

e-mail: testing@govmark.com

Page 2

Received: 09/01/2015 | Completed: 09/15/2015 | Letter: P CT | P.O.#: Test Report #: 3-09555-0-Client's Product Description: Photo Tex Self-Adhesive. Identification Tested For: Walter Gierlach **Key Test:** ASTM E 84 (BLDG) 1185 Photo Tex Group Inc. 4030 Simon Road Tel: 1-(330)-783-0083 Ext: Fax: 1-(330)-783-0761 Boardman, OH 44512

## RESULTS:

Flame Spread Index: 15 Smoke Developed: 15

CONCLUSION: Based on the above Results and Code Classification System the item tested is assigned a:

- [x] Class I or A rating
- [ ] Class II or B rating
- [ ] Class III or C rating
- [ ] Fails to achieve a minimum classification thereby rendering the product unsuitable in terms of code requirement

## DATA SUMMARY:

Time to Ignition: 00.10 minutes Maximum Flame Spread "Distance": 03.49 feet Maximum Flame Spread "Time": 01.40 minutes

## CODE CLASSIFICATION SYSTEM:

Flame Spread Index Smoke Developed \_\_\_\_\_ Class I or A: 0 - 25 450 or less Class II or B: 26 - 75 450 or less Class III or C: 76 - 200 450 or less

BUILDING CODE CITATION FOR THE CLASSIFICATION SCHEME (See "DISCUSSION" on Page 3):

- (1) 2015 edition, NFPA 101 Life Safety Code, para. 10.2.3.4
- (2) 2015 edition, NFPA 5000 Building Construction & Safety Code, para. 10.4.2
- (3) 2015 edition, International Building Code, para. 803.1.1

CERTIFICATION: I certify that the bove results were obtained after testing specimens in accordance with the procedures and equipment pecified above.

AUTHORIZED SIGNATURE

GOVMARK /bg CT /pm

Robert I. Brown
SEP 1 8 2015